DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 99.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-023845 Address: 333 Burma Road **Date Inspected:** 23-Jan-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai

CWI Name: Tian Lei, Liu Fa Wen **CWI Present:** Yes No **Inspected CWI report:** Yes **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector R. Hernandez was present during the time noted above and conducted observations relative to the work being performed.

The QA Inspector randomly observed the following work in progress:

Bay Number 3

The following components were in the above noted bay: AH3152A and AH3151A. This inspector did not any work being performed on these components.

This inspector observed ZPMC QC personnel performing DCP verification and inspection on the following components: 20TR2-32.

Bay Number 8

SMAW welding of complete join penetration welds located on Bike Path component identified as BK004A8-063 for weld no.(s) 001, 002, 007, & 130. Welder is identified as welder no. 066155. The welding variables recorded by ZPMC QC identified as Liu Fa Wen appeared to comply with applicable WPS(s) WPS-B-P-2213-TC-U4b & WPS-B-P-2212-Tc-U4b.

FCAW welding of complete join penetration welds located on Bike Path component identified as BK004A6-063

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

for weld no.(s) 001, 002, 007, & 165. Welder is identified as welder no. 054459. The welding variables recorded by ZPMC QC identified as Liu Fa Wen appeared to comply with applicable WPS(s) WPS-B-T-2132-ESAB & WPS-B-T-2133-ESAB.

This inspector observed ZPMC QC personnel performing MT verification and inspection on the following components: BK004A6-059.

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. All components were as listed on NWIT notification no. 08266. The member(s) is/are identified as OBG Bike Path identified as components BK004A6-063 & BK004A8-063 with the following weld no.(s):

- 1. BK004A4-062-014, 015, 040, & 041.
- 2. BK004A5-062-078, 079, 058, 059, 060, 061, 036, 037, 042, & 043.
- 3. BK004A6-062-041, 042, 117, 118, 033, 034, 043, & 162.
- 4. BK004A7-062-031, 032, 049, 050, 055, 056, 013, 014, 079, & 080.
- 5. BK004A8-062-043, 044, 033, 034, 117, & 118.

This QA inspector performed VT of approximately 100% of the area previously tested and accepted by ZPMC Quality Control personnel. All components were as listed on NWIT notification no. 08269. The member(s) is/are identified as OBG Bike Path identified as components BK4A-063.

Unless otherwise noted above all items observed on this day appeared to be in general compliance with the applicable contract documents



Summary of Conversations:

Pertinent conversations are included in the body of the report.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 1500-0042-02372, who represents the Office of Structural Materials for

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

your project.

Inspected By: Hernandez, Rene Quality Assurance Inspector

Reviewed By: Hall,Steven QA Reviewer